

VOLKSWAGEN CADDY MAXI 2.0 AC EURO6



Itemno 313515
 Kind Van
 Specification Compact panel van
 Matriculation year 2021 / 05
 Mileage 183,121 km

Chassisnumber
 WV1ZZZSKZMX026695

Technical condition

Remarks
 AC 100 PK EURO6 NAVI
 (A15)



Price €13450

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
 P.O. Box 3
 4214 ZJ Vuren
 Zeiving 12
 4214 KT Vuren
 The Netherlands

IBAN: NL32RABO0317847430
 SWIFT/BIC: RABONL2U

KvK 11044363
 BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles 2
 Configuration 4x2
 Loading Capacity 844 kg
 Own weight 1,456 kg
 Gross vehicle weight 2,300 kg
 Unbraked towing capacity 750 kg
 Braked towing capacity, center axle 1,500 kg
 Wheelbase 300 cm
 Suspension type coil spring suspension

Cabin

Cabin type single cabin
 Cruise control
 Airconditioning
 Number of airbags 2
 Parking assistance Front and back
 Coloured windows
 Electric windows
 Electric mirrors
 Partition
 GPS navigation
 Color Silver
 Metallic
 Heated mirrors

Drivetrain

Engine capacity 75 Kw (102 Hp)
 Fuel type diesel
 Euro 6
 Distribution type Timing belt
 Gearbox kind Manual
 Number of Gears 6
 Power steering
 ABS
 ASR

Superstructure

Build kind L2H1 – Middellange wielbasis, laag dak
 Inner box length 220 cm
 Inner box width 145 cm
 Inner box height 121 cm
 Load bed height 60 cm
 Roof-rack None
 Back doors Double door

Chairs

Number of seats 2
 Seat cover cloth

Remarks

Remarks AC 100 PK EURO6 NAVI

Contact information




info@kleyn.com
 Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP TRUCKS TRAILERS SERVICES

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



1
Tire size: 205/60R16,0
coil spring suspension
Disc brakes



2
Tire size: 205/60R16,0
coil spring suspension
Disc brakes

Contact information



info@kleyn.com
Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements