

FIAT DUCATO 2.3 FULL CLIMA NAVI EUR6



Itemno 313620
Kind Van
Specification Closed Van
Matriculation year 2021 / 04
Mileage 80,446 km

Chassisnumber
ZFA25000002R47084

Technical condition

Remarks
FULL CLIMA NAVI CAMERA EURO6
(A15)



Price €18950

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

| | |
|-------------------------------------|-------------------|
| Number of axles | 2 |
| Configuration | 4x2 |
| Loading Capacity | 980 kg |
| Own weight | 2,060 kg |
| Gross vehicle weight | 3,040 kg |
| Unbraked towing capacity | 750 kg |
| Braked towing capacity, center axle | 2,500 kg |
| Towing bracket | |
| Wheelbase | 345 cm |
| Suspension type | spring suspension |

Cabin

| | |
|--------------------|--------------|
| Cabin type | single cabin |
| Cruise control | |
| Airconditioning | |
| Number of airbags | 1 |
| Parking assistance | Back |
| Electric windows | |
| Electric mirrors | |
| Partition | |
| GPS navigation | |
| Color | Black |
| Metallic | |
| Reversing camera | |

Drivetrain

| | |
|-------------------|----------------|
| Engine capacity | 88 Kw (120 Hp) |
| Fuel type | diesel |
| Euro | 6 |
| Distribution type | Timing belt |
| Gearbox kind | Manual |
| Number of Gears | 6 |
| Power steering | |
| ABS | |
| ASR | |

Superstructure

| | |
|------------------|--------------------------------------|
| Build kind | L2H2 - Medium wheelbase, Medium roof |
| Inner box length | 300 cm |
| Inner box width | 188 cm |
| Inner box height | 191 cm |
| Load bed height | 58 cm |
| Roof-rack | None |
| Back doors | Double door |

Chairs

| | |
|-----------------|-------|
| Number of seats | 3 |
| Seat cover | cloth |

Remarks

| | |
|---------|------------------------------|
| Remarks | FULL CLIMA NAVI CAMERA EURO6 |
|---------|------------------------------|

Tyres/Wheels

| | |
|--------------------|------|
| Sparewheel | |
| Spare tire profile | 5 mm |

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



1

Tire size: 215/75R16,0
coil spring suspension
Disc brakes



2

Tire size: 215/75R16,0
spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements