VOLKSWAGEN CRAFTER 35 2.0 L3H2 LED Automa:



314741 Itemno Kind Van Specification Closed Van Matriculation year 2024 / 12 Mileage 11 km

Chassisnumber WV1ZZZSY5S9023492

Technical condition







Remarks L3H2 (L2H1) LED 177Pk Facelift Clima (A15)

Price €43850



Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles Configuration 4x2 Loading Capacity 1,441 kg Own weight 2,059 kg Gross vehicle weight 3,500 kg Unbraked towing capacity 750 kg Braked towing capacity, center 3,000 kg

Wheelbase 364 cm

Suspension type spring suspension

Cabin

Cabin type single cabin

Cruise control Airconditioning

Number of airbags

Front and back Parking assistance

Electric windows Electric mirrors Partition

GPS navigation

Color Silver

Metallic

Heated mirrors Reversing camera

Drivetrain

Engine capacity 130 Kw (177 Hp)

Fuel type diesel Euro

Timing belt Distribution type Gearbox kind Automatic

Power steering

ABS **ASR**

Superstructure

Inner box length 325 cm Inner box width 178 cm 173 cm Inner box heigth Load bed heigth 60 cm Netto height 160 cm

Rear step

Roof-rack None Sidedoors

Back doors Double door

Chairs

Number of seats 3 Seat cover cloth Comfort seat left

Remarks

Remarks L3H2 (L2H1) LED 177Pk

Facelift Clima Automaat Euro6

Nieuw BPM-VRIJ Direct-Leverbaar!

Tyres/Wheels

Sparewheel

Spare tire profile 8 mm

Contact information



info@kleyn.com Tel: +31 183 668 444

Certified and professional
















Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



VANS

GROUP TRUCKS

KLEYN



Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin
Internal
External
Steering column
Suspension
Chassis
Wheelsuspension
Brakes

Drivetrain

Engine, general 99999 Cooling system 00000 33333 Fuel system 00000 Exhaust system Greasing system 99999 Gearbox 00000 Clutch 33333 Drivetrain 00000

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



Tire size: 205/65R16,0 coil spring suspension Disc brakes



Tire size: 205/65R16,0 spring suspension Disc brakes

Contact information



info@kleyn.com Tel: +31 183 668 444

Legenda for inspection report

Very good state
Good state
Reasonable state
Moderate state

Does not meet requirements