

# MERCEDES-BENZ VITO 114 CDI LONG SELECT



Itemno 315186  
 Kind Van  
 Specification Closed Van  
 Matriculation year 2020 / 07  
 Mileage 104,111 km

**Chassisnumber**  
 W1V44760313755613

Technical condition

**Remarks**  
 lang, airco, navi, imperiaal, trap  
 ( A15 )



**Price €17900**

Kleyn Vans B.V.®  
 P.O. Box 3  
 4214 ZJ Vuren  
 Zeiving 12  
 4214 KT Vuren  
 The Netherlands

IBAN: NL32RABO0317847430  
 SWIFT/BIC: RABONL2U

KvK 11044363  
 BTW/VAT NL807901337B01

## Equipment

### Chassis

Number of axles 2  
 Configuration 4x2  
 Own weight 1,984 kg  
 Gross vehicle weight 2,800 kg  
 Wheelbase 320 cm  
 Suspension type coil spring suspension

### Cabin

Cabin type single cabin  
 Cruise control  
 Airconditioning  
 Number of airbags 2  
 Parking assistance None  
 Electric windows  
 Electric mirrors  
 Partition  
 GPS navigation  
 Color white  
 maintenance Guide  
 Heated mirrors  
 Reversing camera

### Drivetrain

Engine capacity 100 Kw (136 Hp)  
 Fuel type diesel  
 Euro 6  
 Distribution type Timing chain  
 Gearbox kind Manual  
 Number of Gears 6  
 Power steering  
 ABS  
 ASR

### Superstructure

Inner box length 250 cm  
 Inner box width 168 cm  
 Inner box height 133 cm  
 Load bed height 58 cm  
 Netto height 123 cm  
 Roof-rack with roll and stairs  
 Sidedoors 1  
 Back doors Double door

### Chairs

Number of seats 3  
 Seat cover cloth

### Remarks

Remarks lang, airco, navi, imperiaal, trap

### Tyres/Wheels

Sparewheel  
 Spare tire profile 6 mm

### Contact information




info@kleyn.com  
 Tel: +31 183 668 444

### Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

## Dimensions



# KLEYN VANS

**KLEYN** GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®  
P.O. Box 3  
4214 ZJ Vuren  
Zeiving 12  
4214 KT Vuren  
The Netherlands

IBAN: NL32RABO0317847430  
SWIFT/BIC: RABONL2U

KvK 11044363  
BTW/VAT NL807901337B01

## Inspection report

### Chassis

Dashboard display codes

Electrical

### Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

### Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

### Superstructure

Internal condition

External condition

### Tyres/Wheels

Tyres

## Tires and axles



Tire size: 195/65R16,0  
coil spring suspension  
Disc brakes



Tire size: 195/65R16,0  
coil spring suspension  
Disc brakes

### Contact information



info@kleyn.com  
Tel: +31 183 668 444

### Legenda for inspection report

Very good state  
 Good state  
 Reasonable state  
 Moderate state  
 Does not meet requirements