

IVECO DAILY 35C16 Bakwagen Laadklep!



Itemno 315695
 Kind Van
 Specification Closed box
 Matriculation year 2022 / 08
 Mileage 99,253 km

Chassisnumber
 ZCFCC35B505474151

Technical condition

Remarks
 Bakwagen Laadklep, Dubbellucht, Airco,
 (A15)

Price €26800

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
 P.O. Box 3
 4214 ZJ Vuren
 Zeiving 12
 4214 KT Vuren
 The Netherlands

IBAN: NL32RABO0317847430
 SWIFT/BIC: RABONL2U

KvK 11044363
 BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles 2
 Configuration 4x2
 Twin tires
 Loading Capacity 890 kg
 Own weight 2,610 kg
 Gross vehicle weight 3,500 kg
 Unbraked towing capacity 750 kg
 Braked towing capacity, center axle 3,500 kg
 Wheelbase 410 cm
 Suspension type spring suspension

Cabin

Cabin type single cabin
 Cruise control
 Airconditioning
 Number of airbags 1
 Parking assistance None
 Electric windows
 Electric mirrors
 Color white
 Heated mirrors

Drivetrain

Engine capacity 115 Kw (156 Hp)
 Fuel type diesel
 Euro 6
 Distribution type Timing belt
 Gearbox kind Manual
 Number of Gears 6
 Power steering
 ABS
 ASR

Superstructure

Inner box length 436 cm
 Inner box width 205 cm
 Inner box height 210 cm
 Load bed height 93 cm
 Netto height 205 cm
 Roof-rack None
 Back doors taillift

Chairs

Number of seats 3
 Seat cover cloth

Taillift

Taillift
 Tail-lift kind normal
 Tail-lift capacity 750 kg
 Tail-lift make Palfinger
 Tail-lift size 160x208

Remarks

Remarks Bakwagen Laadklep,
 Dubbellucht, Airco, Euro 6, 160
 PK!

Contact information




info@kleyn.com
 Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP KLEYN TRUCKS KLEYN TRAILERS KLEYN SERVICES

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Taillift

Controls

System

Tyres/Wheels

Tyres

Tires and axles



Tire size: 195/75R16,0
torsion spring suspension
Disc brakes



Tire size: 195/75R16,0
spring suspension
Disc brakes

Contact information



info@kleyn.com
Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements