

## RENAULT MASTER 2.3 Open-Laadbak XXXL!



Itemno 315732  
Kind Van  
Specification Open with sideboards  
Matriculation year 2019 / 01  
Mileage 183,405 km

**Chassisnumber**  
VF6VG000561821804

Technical condition

**Remarks**  
Open-Laadbak XXL, 5 mtr, airco, navi, 3.5  
( A15 )

**Price €17800**

# KLEYN VANS

**KLEYN GROUP** **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®  
P.O. Box 3  
4214 ZJ Vuren  
Zeiving 12  
4214 KT Vuren  
The Netherlands

IBAN: NL32RABO0317847430  
SWIFT/BIC: RABONL2U

KvK 11044363  
BTW/VAT NL807901337B01

## Equipment

### Chassis

Number of axles	2
Configuration	4x2
Twin tires	
Loading Capacity	450 kg
Own weight	3,050 kg
Gross vehicle weight	3,500 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	3,500 kg
Towing bracket	
Wheelbase	433 cm
Suspension type	spring suspension

### Cabin

Cabin type	single cabin
Cruise control	
Airconditioning	
Number of airbags	1
Parking assistance	None
Electric windows	
Electric mirrors	
GPS navigation	
Color	Black
Heated mirrors	

### Drivetrain

Engine capacity	120 Kw (163 Hp)
Fuel type	diesel
Euro	6
Distribution type	Timing chain
Gearbox kind	Manual
Number of Gears	6
Power steering	
ABS	
ASR	

### Superstructure

Inner box length	481 cm
Inner box width	211 cm
Inner box height	40 cm
Load bed height	81 cm
Rear step	
Roof-rack	None
Back doors	taillift

### Chairs

Number of seats	3
Seat cover	cloth

### Remarks

Remarks	Open-Laadbak XXL, 5 mtr, airco, navi, 3.5 ton trekhaak, Euro6!
---------	--

### Tyres/Wheels

Sparewheel	
Spare tire profile	8 mm

### Contact information




info@kleyn.com  
Tel: +31 183 668 444

### Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

## Dimensions



# KLEYN VANS

**KLEYN GROUP** **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®  
P.O. Box 3  
4214 ZJ Vuren  
Zeiving 12  
4214 KT Vuren  
The Netherlands

IBAN: NL32RABO0317847430  
SWIFT/BIC: RABONL2U

KvK 11044363  
BTW/VAT NL807901337B01

## Inspection report

### Chassis

Dashboard display codes

Electrical

### Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

### Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

### Superstructure

Internal condition

External condition

### Tyres/Wheels

Tyres

## Tires and axles



1  
Tire size: 195/75R16,0  
coil spring suspension  
Disc brakes



2  
Tire size: 195/75R16,0  
spring suspension  
Disc brakes

### Contact information



info@kleyn.com  
Tel: +31 183 668 444

### Legenda for inspection report

Very good state  
 Good state  
 Reasonable state  
 Moderate state  
 Does not meet requirements