

MERCEDES-BENZ VITO 114 L3 XL Dubbel Cabine!



Itemno 315862
 Kind Van
 Specification Closed Van
 Matriculation year 2021 / 04
 Mileage 165,153 km

Chassisnumber
 W1V44760513859979

Technical condition 

Remarks
 L3 XL Dubbel Cabine Airco/ECC Automaat
 (A15)



Price €25450

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
 P.O. Box 3
 4214 ZJ Vuren
 Zeiving 12
 4214 KT Vuren
 The Netherlands

IBAN: NL32RABO0317847430
 SWIFT/BIC: RABONL2U

KvK 11044363
 BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles 2
 Configuration 4x2
 Loading Capacity 746 kg
 Own weight 2,054 kg
 Gross vehicle weight 2,800 kg
 Unbraked towing capacity 750 kg
 Braked towing capacity, center axle 2,500 kg
 Towing bracket
 Wheelbase 343 cm
 Aluminium rims
 Suspension type coil spring suspension

Cabin

Cabin type double cabin
 Cruise control
 Airconditioning
 Number of airbags 2
 Parking assistance Front and back
 Electric windows
 Electric mirrors
 Partition
 Color white
 Heated mirrors

Drivetrain

Engine capacity 100 Kw (136 Hp)
 Fuel type diesel
 Euro 6
 Distribution type Timing chain
 Gearbox kind Automatic
 Power steering
 ABS
 ASR

Superstructure

Inner box length 186 cm
 Inner box width 163 cm
 Inner box height 132 cm
 Load bed height 55 cm
 Netto height 126 cm
 Roof-rack standard
 Sidedoors 1
 Side windows 2
 Back doors Double door

Chairs

Number of seats 5
 Seats configuration 2+3
 Seat cover cloth

Remarks

Remarks L3 XL Dubbel Cabine
 Airco/ECC Automaat Euro6
 NAP Bumpers-Kleur
 Lm-Velgen!

Contact information




info@kleyn.com
 Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP KLEYN TRUCKS KLEYN TRAILERS KLEYN SERVICES

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



Tire size: 225/55R17,0
coil spring suspension
Disc brakes



Tire size: 225/55R17,0
coil spring suspension
Disc brakes

Contact information



info@kleyn.com
Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements