OPEL MOVANO 2.3 L3H2 LED Airco!



315901 Itemno Kind Van Specification Closed Van Matriculation year 2024 / 10 Mileage 16 km

Chassisnumber

VXEYCG6F6RMA03296

Technical condition

Price € 26900







(A15)



Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles Configuration 4x2 Loading Capacity 1,445 kg Own weight 2,055 kg Gross vehicle weight 3,500 kg Unbraked towing capacity 750 kg Braked towing capacity, center 2,500 kg

Wheelbase 404 cm

Suspension type spring suspension

Cabin

Cabin type single cabin

Cruise control Airconditioning

2 Number of airbags Back Parking assistance

Electric windows Electric mirrors

Partition

Color white

Heated mirrors Reversing camera

Drivetrain

Engine capacity 132 Kw (179 Hp)

Fuel type diesel Euro

Distribution type Timing chain Gearbox kind Manual Number of Gears 6

Power steering

ABS **ASR**

Superstructure

Inner box length 358 cm Inner box width 186 cm 193 cm Inner box heigth Load bed heigth 58 cm Netto height 181 cm Roof-rack None Sidedoors

Back doors Double door

Chairs

Number of seats 3 Seat cover cloth

Remarks

Remarks L3H2, Airco, PDC, Camera,

LED, Cruise, 180 PK, Euro 6

Tyres/Wheels

Sparewheel

Spare tire profile 10 mm

Contact information



info@kleyn.com Tel: +31 183 668 444

Certified and professional












Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions





EYN KLEYN KL

TRAILERS

SERVICES

Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin
Internal
External
Steering column
Suspension
Chassis
Wheelsuspension
Brakes

Drivetrain

Engine, general 99999 Cooling system 00000 33333 Fuel system 00000 Exhaust system Greasing system 99999 Gearbox 00000 Clutch 33333 Drivetrain 00000

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



Tire size: 215/70R15,0 coil spring suspension Disc brakes



Tire size: 215/70R15,0 spring suspension Disc brakes

Contact information



info@kleyn.com Tel: +31 183 668 444

Legenda for inspection report

Very good state
Good state
Reasonable state
Moderate state

Does not meet requirements