

MERCEDES-BENZ VITO 114 L2H1 Automaat Navi !



Itemno 316011
Kind Van
Specification Closed Van
Matriculation year 2021 / 12
Mileage 142,284 km

Chassisnumber
W1V44760313865987

Technical condition

Remarks
lang, automaat, airco, navi, cruise, trekhaak
(A15)

Price € 21900

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles 2
Configuration 4x2
Own weight 2,089 kg
Gross vehicle weight 3,050 kg
Towing bracket √
Wheelbase 320 cm
Suspension type coil spring suspension

Cabin

Cabin type single cabin
Cruise control √
Airconditioning √
Parking heater √
Number of airbags 2
Parking assistance None
Electric windows √
Electric mirrors √
Partition √
GPS navigation √
Color white
maintenance Guide √
Reversing camera √

Drivetrain

Engine capacity 100 Kw (136 Hp)
Fuel type diesel
Euro 6
Distribution type Timing chain
Gearbox kind Automatic
Power steering √
ABS √
ASR √

Superstructure

Inner box length 246 cm
Inner box width 164 cm
Inner box height 135 cm
Load bed height 57 cm
Netto height 121 cm
Roof-rack None
Sidedoors 1
Back doors Double door

Chairs

Number of seats 3
Seat cover leather

Remarks

Remarks lang, automaat, airco, navi, cruise, trekhaak

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



Tire size: 205/65R16,0
coil spring suspension
Disc brakes



Tire size: 205/65R16,0
coil spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements