

FORD TRANSIT CONNECT L2 Navi NAP Euro6 AC



Itemno 316203
 Kind Van
 Specification Compact panel van
 Matriculation year 2019 / 08
 Mileage 69,003 km

Chassisnumber
 WF0SXXWPGSKL22989

Technical condition

Remarks
 L2 Navi Airco 100Pk Trekhaak Camera 1e
 (A15)



Price €14800



Kleyn Vans B.V.®
 P.O. Box 3
 4214 ZJ Vuren
 Zeiving 12
 4214 KT Vuren
 The Netherlands

IBAN: NL32RABO0317847430
 SWIFT/BIC: RABONL2U

KvK 11044363
 BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles 2
 Configuration 4x2
 Loading Capacity 814 kg
 Own weight 1,591 kg
 Gross vehicle weight 2,405 kg
 Unbraked towing capacity 750 kg
 Braked towing capacity, center axle 1,136 kg
 Towing bracket
 Wheelbase 306 cm
 Suspension type coil spring suspension

Cabin

Cabin type single cabin
 Cruise control
 Airconditioning
 Number of airbags 2
 Parking assistance Back
 Electric windows
 Electric mirrors
 Partition
 GPS navigation
 Color white
 maintenance Guide
 Heated mirrors

Drivetrain

Engine capacity 73 Kw (99 Hp)
 Fuel type diesel
 Euro 6
 Distribution type Timing belt
 Gearbox kind Manual
 Number of Gears 6
 Power steering
 ABS
 ASR

Superstructure

Inner box length 204 cm
 Inner box width 128 cm
 Inner box height 121 cm
 Load bed height 57 cm
 Netto height 114 cm
 Roof-rack with roll
 Sidedoors 1
 Back doors Double door

Chairs

Number of seats 2
 Seat cover cloth

Remarks

Remarks L2 Navi Airco 100Pk Trekhaak
 Camera 1e Eigenaar
 oh-Historie NAP Imperiaal
 Euro6!

Tyres/Wheels

Sparewheel
 Spare tire profile 9 mm

Contact information




info@kleyn.com
 Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP KLEYN TRUCKS KLEYN TRAILERS KLEYN SERVICES

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



1
Tire size: 215/55R16,0
coil spring suspension
Disc brakes



2
Tire size: 215/55R16,0
coil spring suspension
Disc brakes

Contact information



info@kleyn.com
Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements