

# VOLKSWAGEN CADDY 2.0 L1 Carplay Euro6 AC!



Itemno 317906  
 Kind Van  
 Specification Compact panel van  
 Matriculation year 2023 / 01  
 Mileage 150,087 km

**Chassisnumber**  
 WV1ZZZSK5PX047354

Technical condition

**Remarks**  
 L1 Carplay Euro6 Airco 75Pk NAP!  
 ( A15 )



**Price €13600**



Kleyn Vans B.V.®  
 P.O. Box 3  
 4214 ZJ Vuren  
 Zeiving 12  
 4214 KT Vuren  
 The Netherlands

IBAN: NL32RABO0317847430  
 SWIFT/BIC: RABONL2U

KvK 11044363  
 BTW/VAT NL807901337B01

## Equipment

### Chassis

Number of axles 2  
 Configuration 4x2  
 Loading Capacity 810 kg  
 Own weight 1,410 kg  
 Gross vehicle weight 2,220 kg  
 Unbraked towing capacity 740 kg  
 Braked towing capacity, center axle 1,400 kg  
 Wheelbase 276 cm  
 Suspension type coil spring suspension

### Cabin

Cabin type single cabin  
 Cruise control  
 Airconditioning  
 Number of airbags 2  
 Rear wiper  
 Parking assistance None  
 Electric windows  
 Electric mirrors  
 Partition  
 Color white  
 Reversing camera

### Drivetrain

Engine capacity 55 Kw (75 Hp)  
 Fuel type diesel  
 Euro 6  
 Distribution type Timing belt  
 Gearbox kind Manual  
 Number of Gears 6  
 Power steering  
 ABS  
 ASR

### Superstructure

Inner box length 165 cm  
 Inner box width 142 cm  
 Inner box height 122 cm  
 Load bed height 56 cm  
 Netto height 110 cm  
 Roof-rack None  
 Sidedoors 1  
 Back doors Double door

### Chairs

Number of seats 2  
 Seat cover cloth

### Remarks

Remarks L1 Carplay Euro6 Airco 75Pk NAP!

### Tyres/Wheels

Sparewheel

### Contact information




info@kleyn.com  
 Tel: +31 183 668 444

### Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

## Dimensions



# KLEYN VANS

**KLEYN** GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®  
P.O. Box 3  
4214 ZJ Vuren  
Zeiving 12  
4214 KT Vuren  
The Netherlands

IBAN: NL32RABO0317847430  
SWIFT/BIC: RABONL2U

KvK 11044363  
BTW/VAT NL807901337B01

## Inspection report

### Chassis

Dashboard display codes

Electrical

### Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

### Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

### Superstructure

Internal condition

External condition

### Tyres/Wheels

Tyres

## Tires and axles



1  
Tire size: 205/65R15,0  
coil spring suspension  
Disc brakes



2  
Tire size: 205/65R15,0  
coil spring suspension  
Disc brakes

### Contact information



info@kleyn.com  
Tel: +31 183 668 444

### Legenda for inspection report

Very good state  
 Good state  
 Reasonable state  
 Moderate state  
 Does not meet requirements