

CITROEN JUMPY 2.0 L2 177Pk Euro6 AC!



Itemno 318012
Kind Van
Specification Closed Van
Matriculation year 2019 / 09
Mileage 123,071 km

Chassisnumber
VF7VFEHZ8KZ076813

Technical condition

Remarks
L2 177Pk Euro6 Airco Head-Up Camera
(A15)

Price € 16900

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles 2
Configuration 4x2
Own weight 1,756 kg
Gross vehicle weight 2,760 kg
Towing bracket √
Wheelbase 328 cm
Aluminium rims √
Suspension type coil spring suspension

Cabin

Cabin type single cabin
Cruise control √
Airconditioning √
Number of airbags 1
Rear wiper √
Parking assistance Front and back
Electric windows √
Electric mirrors √
Partition √
Color Black
maintenance Guide √
Reversing camera √

Drivetrain

Engine capacity 130 Kw (177 Hp)
Fuel type diesel
Euro 6
Distribution type Timing belt
Gearbox kind Automatic
Power steering √
ABS √
ASR √

Superstructure

Inner box length 255 cm
Inner box width 158 cm
Inner box height 130 cm
Load bed height 60 cm
Netto height 123 cm
Roof-rack None
Sidedoors 1
Back doors Double door

Chairs

Number of seats 3
Seat cover cloth

Remarks

Remarks L2 177Pk Euro6 Airco Head-Up
Camera Trekhaak
Stoelverwarming 1e Eigenaar!

Tyres/Wheels

Sparewheel √

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



Tire size: 215/60R17,0
coil spring suspension
Disc brakes



Tire size: 215/60R17,0
coil spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements