

## VOLKSWAGEN CRAFTER 2.0 TDI L2H1



Itemno 318131  
Kind Van  
Specification Closed Van  
Matriculation year 2016 / 09  
Mileage 205,461 km

Chassisnumber  
WV1ZZZ2EZG6049125

Technical condition

Remarks  
L2H1, airco, pdc  
( A15 )



**Price € 8800**

# KLEYN VANS

**KLEYN** GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®  
P.O. Box 3  
4214 ZJ Vuren  
Zeiving 12  
4214 KT Vuren  
The Netherlands

IBAN: NL32RABO0317847430  
SWIFT/BIC: RABONL2U

KvK 11044363  
BTW/VAT NL807901337B01

## Equipment

### Chassis

|                                     |                   |
|-------------------------------------|-------------------|
| Number of axles                     | 2                 |
| Configuration                       | 4x2               |
| Loading Capacity                    | 701 kg            |
| Own weight                          | 2,099 kg          |
| Gross vehicle weight                | 2,800 kg          |
| Unbraked towing capacity            | 750 kg            |
| Braked towing capacity, center axle | 2,000 kg          |
| Wheelbase                           | 367 cm            |
| Suspension type                     | spring suspension |

### Cabin

|                    |                |
|--------------------|----------------|
| Cabin type         | double cabin   |
| Cruise control     | ✓              |
| Airconditioning    | ✓              |
| Number of airbags  | 1              |
| Parking assistance | Front and back |
| Electric windows   | ✓              |
| Electric mirrors   | ✓              |
| Partition          | ✓              |
| Color              | Black          |
| Metallic           | ✓              |
| Heated mirrors     | ✓              |

### Drivetrain

|                   |                |
|-------------------|----------------|
| Engine capacity   | 80 Kw (109 Hp) |
| Fuel type         | diesel         |
| Euro              | 6              |
| Distribution type | Timing belt    |
| Gearbox kind      | Manual         |
| Number of Gears   | 6              |
| Power steering    | ✓              |
| ABS               | ✓              |
| ASR               | ✓              |

### Superstructure

|                  |             |
|------------------|-------------|
| Inner box length | 330 cm      |
| Inner box width  | 176 cm      |
| Inner box height | 168 cm      |
| Load bed height  | 78 cm       |
| Netto height     | 152 cm      |
| Roof-rack        | None        |
| Sidedoors        | 1           |
| Back doors       | Double door |

### Chairs

|                 |       |
|-----------------|-------|
| Number of seats | 3     |
| Seat cover      | cloth |
| Comfort seat    | left  |

### Remarks

|         |                  |
|---------|------------------|
| Remarks | L2H1, airco, pdc |
|---------|------------------|

### Tyres/Wheels

|                    |      |
|--------------------|------|
| Sparewheel         | ✓    |
| Spare tire profile | 3 mm |

### Contact information




info@kleyn.com  
Tel: +31 183 668 444

### Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

## Dimensions



# KLEYN VANS

**KLEYN** GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

## Inspection report

### Chassis

Dashboard display codes

Electrical

### Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

### Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

### Superstructure

Internal condition

External condition

### Tyres/Wheels

Tyres

## Tires and axles



1  
Tire size: 205/75R16,0  
spring suspension  
Disc brakes



2  
Tire size: 205/75R16,0  
spring suspension  
Disc brakes

### Contact information



info@kleyn.com

Tel: +31 183 668 444

### Legenda for inspection report

Very good state  
 Good state  
 Reasonable state  
 Moderate state  
 Does not meet requirements