

## VOLKSWAGEN CADDY 1.4 TSI BENZINE



Itemno 311974  
Kind Van  
Specification Frigo  
Matriculation year 2020 / 01  
Mileage 74,614 km

**Chassisnumber**  
WV1ZZZ2KZLX048529

Technical condition

**Remarks**  
KOELING DAG/NACHT THERMOKING  
( A15 )

**Price €19950**

# KLEYN VANS

**KLEYN GROUP** **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®  
P.O. Box 3  
4214 ZJ Vuren  
Zeiving 12  
4214 KT Vuren  
The Netherlands

IBAN: NL32RABO0317847430  
SWIFT/BIC: RABONL2U

KvK 11044363  
BTW/VAT NL807901337B01

## Equipment

### Chassis

Number of axles 2  
Configuration 4x2  
Loading Capacity 615 kg  
Own weight 1,660 kg  
Gross vehicle weight 2,275 kg  
Wheelbase 300 cm  
Suspension type spring suspension

### Cabin

Cabin type single cabin  
Cruise control  
Airconditioning  
Number of airbags 4  
Parking assistance Back  
Coloured windows  
Electric windows  
Electric mirrors  
Partition  
Color white  
Heated mirrors

### Drivetrain

Engine capacity 96 Kw (130 Hp)  
Fuel type petrol  
Euro 6  
Distribution type Timing chain  
Gearbox kind Automatic  
Number of Gears 6  
Power steering  
ABS  
ASR

### Superstructure

Build kind L2H1 – Middellange wielbasis, laag dak  
Inner box length 202 cm  
Inner box width 125 cm  
Inner box height 108 cm  
Load bed height 62 cm  
Netto height 106 cm  
Roof-rack None  
Sidedoors 1  
Back doors Double door

### Chairs

Number of seats 2  
Seat cover cloth

### Refrigeration unit

Enginemake frigo-unit Thermoking  
Enginetype frigo-unit b-100 max  
Enginetype frigo-unit Compressor / electrical  
Isolated box  
Type of cooling Cooling  
Day/night cooling day and night cooling

### Remarks

Remarks KOELING DAG/NACHT THERMOKING BENZINE!

### Contact information




info@kleyn.com  
Tel: +31 183 668 444

### Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

## Dimensions



# KLEYN VANS

**KLEYN GROUP** **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

## Inspection report

### Chassis

Dashboard display codes

Electrical

### Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

### Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

### Superstructure

Internal condition

External condition

### Refrigeration unit

Systems

### Tyres/Wheels

Tyres

## Tires and axles



1

Tire size: 205/55R16,0  
coil spring suspension  
Disc brakes



2

Tire size: 205/55R16,0  
spring suspension  
Disc brakes

### Contact information



info@kleyn.com

Tel: +31 183 668 444

### Legenda for inspection report

- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements