

MERCEDES-BENZ ESPRINTER L2H2 47 kWh Airco!



Itemno 315582
Kind Van
Specification Closed Van
Matriculation year 2024 / 10
Mileage 68 km

Chassisnumber
W1V9106331P457179

Technical condition

Remarks
L2H2, Automaat, 143 km WLTP, Camera,
(A15)

Price € 29450

KLEYN VANS

KLEYN **KLEYN** **KLEYN** **KLEYN**
GROUP TRUCKS TRAILERS SERVICES

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles 2
Configuration 4x2
Loading Capacity 793 kg
Own weight 2,707 kg
Gross vehicle weight 3,500 kg
Wheelbase 392 cm
Aluminium rims ✓
Suspension type spring suspension

Cabin

Cabin type single cabin
Airconditioning ✓
Number of airbags 6
Rear wiper ✓
Parking assistance None
Coloured windows ✓
Electric windows ✓
Electric mirrors ✓
Color Gray
Metallic ✓
Heated mirrors ✓
Reversing camera ✓

Drivetrain

Engine capacity 70 Kw (95 Hp)
Fuel type electrical
Gearbox kind Automatic
Power steering ✓
ABS ✓
ASR ✓

Superstructure

Inner box length 340 cm
Inner box width 176 cm
Inner box height 200 cm
Load bed height 64 cm
Netto height 191 cm
Rear step ✓
Roof-rack None
Sidedoors 1
Side windows 1
Back doors Double door

Chairs

Number of seats 2
Seat cover cloth

Remarks

Remarks
L2H2, Automaat, 143 km
WLTP, Camera, Airco, 47 kWh,
Metallic, 270- gr. Deuren

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



Tire size: 225/75R16,0
coil spring suspension
Disc brakes



Tire size: 225/75R16,0
spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements