

NISSAN NAVARA 2.5 FULL CLIMA 4 X 4



Itemno 316076
Kind Van
Specification Pickup
Matriculation year 2009 / 02
Mileage 288,281 km

Chassisnumber
VSKBVND40U0274085

Technical condition 

Remarks
FULL CLIMA 4X4
(A15)



Price € 8400

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles	2
Configuration	4x4
Loading Capacity	875 kg
Own weight	1,930 kg
Gross vehicle weight	2,805 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	3,000 kg
Towing bracket	✓
Wheelbase	320 cm
Suspension type	spring suspension

Cabin

Cabin type	single cabin
Airconditioning	✓
Number of airbags	2
Parking assistance	None
Electric windows	✓
Electric mirrors	✓
GPS navigation	✓
Color	Black
Heated mirrors	✓
Reversing camera	✓

Drivetrain

Engine capacity	126 Kw (171 Hp)
Fuel type	diesel
Euro	4
Distribution type	Timing chain
Gearbox kind	Manual
Number of Gears	6
Power steering	✓
ABS	✓
ASR	✓

Superstructure

Build kind	L1H1 - Short wheelbase, Low roof
Inner box length	186 cm
Inner box width	149 cm
Inner box height	46 cm
Load bed height	74 cm
Roof-rack	None
Back doors	taillift

Chairs

Number of seats	2
Seat cover	cloth

Remarks

Remarks	FULL CLIMA 4X4
---------	----------------

Tyres/Wheels

Sparewheel	✓
Spare tire profile	4 mm

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



Tire size: 225/70R16,0
coil spring suspension
Disc brakes



Tire size: 225/70R16,0
spring suspension
Drum brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements