


VOLKSWAGEN TRANSPORTER 2.0 TDI 102 KOMBI



Itemno 316605
 Kind Van
 Specification Passenger transport
 Matriculation year 2019 / 06
 Mileage 128,457 km
Chassisnumber
 WV2ZZZ7HZKH085590
 Technical condition 
Remarks
 8+1, KOMBI, lang, airco, BPM, Verkoopprijs
 (A15)

Price €18800

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
 P.O. Box 3
 4214 ZJ Vuren
 Zeiving 12
 4214 KT Vuren
 The Netherlands

IBAN: NL32RABO0317847430
 SWIFT/BIC: RABONL2U

KvK 11044363
 BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles 2
 Configuration 4x2
 Own weight 1,759 kg
 Gross vehicle weight 3,000 kg
 Unbraked towing capacity 750 kg
 Braked towing capacity, center axle 2,200 kg
 Wheelbase 340 cm
 Suspension type coil spring suspension

Cabin

Cruise control
 Airconditioning
 Number of airbags 2
 Rear wiper
 Parking assistance Front and back
 Electric windows
 Electric mirrors
 Color Silver
 Metallic
 Heated mirrors

Drivetrain

Engine capacity 75 Kw (102 Hp)
 Fuel type diesel
 Euro 6
 Distribution type Timing belt
 Gearbox kind Manual
 Number of Gears 5
 Power steering
 ABS
 ASR

Superstructure

Inner box length 109 cm
 Inner box width 156 cm
 Inner box height 135 cm
 Load bed height 57 cm
 Netto height 129 cm
 Roof-rack None
 Sidedoors 1
 Side windows 4
 Back doors taillift

Chairs

Number of seats 9
 Seats configuration 3+3+3
 Seat cover cloth

Remarks

Remarks 8+1, KOMBI, lang, airco, BPM, Verkoopprijs ex btw/BPM.

Tyres/Wheels

Sparewheel
 Spare tire profile 6 mm

Contact information




info@kleyn.com
 Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



Tire size: 205/65R16,0
coil spring suspension
Disc brakes



Tire size: 205/65R16,0
coil spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements