

MERCEDES-BENZ EQV 300 L2 7Prs 90kWh



Itemno 318073
Kind Van
Specification Passenger transport
Matriculation year 2023 / 10
Mileage 19,518 km

Chassisnumber
W1VVKFZ1P4316642

Technical condition

Remarks
300 L2 7Persoons 90kWh Navi Leer
(A15)

Price € 41900

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles 2
Configuration 4x2
Own weight 2,635 kg
Gross vehicle weight 3,500 kg
Wheelbase 320 cm
Aluminium rims ✓
Suspension type coil spring suspension

Cabin

Cruise control ✓
Airconditioning ✓
Number of airbags 6
Rear wiper ✓
Parking assistance Front and back
Coloured windows ✓
Electric windows ✓
Electric mirrors ✓
GPS navigation ✓
Color Black
Metallic ✓
Heated mirrors ✓
Reversing camera ✓

Drivetrain

Engine capacity 70 Kw (95 Hp)
Fuel type electrical
Gearbox kind Automatic
Power steering ✓
ABS ✓
ASR ✓

Superstructure

Inner box length 50 cm
Inner box width 128 cm
Inner box height 119 cm
Load bed height 54 cm
Netto height 121 cm
Roof-rack None
Sidedoors 2
Side windows 4
Back doors taillift

Chairs

Number of seats 7
Seats configuration 2+2+3
Seat cover leather

Remarks

Remarks 300 L2 7Persoons 90kWh Navi Leer BPM-Vrij 100% Elektrisch!

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



Tire size: 245/55R17,0
coil spring suspension
Disc brakes



Tire size: 245/55R17,0
coil spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements