

VOLKSWAGEN CRAFTER 2.0 TDI L2H1



Itemno 318131
Kind Van
Specification Closed Van
Matriculation year 2016 / 09
Mileage 205,461 km

Chassisnumber
WV1ZZZ2EZG6049125

Technical condition

Remarks
L2H1, airco, pdc
(A15)



Price €8800

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

| | |
|-------------------------------------|-------------------|
| Number of axles | 2 |
| Configuration | 4x2 |
| Loading Capacity | 701 kg |
| Own weight | 2,099 kg |
| Gross vehicle weight | 2,800 kg |
| Unbraked towing capacity | 750 kg |
| Braked towing capacity, center axle | 2,000 kg |
| Wheelbase | 367 cm |
| Suspension type | spring suspension |

Cabin

| | |
|--------------------|----------------|
| Cabin type | double cabin |
| Cruise control | |
| Airconditioning | |
| Number of airbags | 1 |
| Parking assistance | Front and back |
| Electric windows | |
| Electric mirrors | |
| Partition | |
| Color | Black |
| Metallic | |
| Heated mirrors | |

Drivetrain

| | |
|-------------------|----------------|
| Engine capacity | 80 Kw (109 Hp) |
| Fuel type | diesel |
| Euro | 6 |
| Distribution type | Timing belt |
| Gearbox kind | Manual |
| Number of Gears | 6 |
| Power steering | |
| ABS | |
| ASR | |

Superstructure

| | |
|------------------|-------------|
| Inner box length | 330 cm |
| Inner box width | 176 cm |
| Inner box height | 168 cm |
| Load bed height | 78 cm |
| Netto height | 152 cm |
| Roof-rack | None |
| Sidedoors | 1 |
| Back doors | Double door |

Chairs

| | |
|-----------------|-------|
| Number of seats | 3 |
| Seat cover | cloth |
| Comfort seat | left |

Remarks

| | |
|---------|------------------|
| Remarks | L2H1, airco, pdc |
|---------|------------------|

Tyres/Wheels

| | |
|--------------------|------|
| Sparewheel | |
| Spare tire profile | 3 mm |

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



1

Tire size: 205/75R16,0
spring suspension
Disc brakes



2

Tire size: 205/75R16,0
spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements