

## RENAULT TRAFIC 2.0 DCI L1H1



Itemno 318332  
Kind Van  
Specification Closed Van  
Matriculation year 2008 / 09  
Mileage 482,231 km

**Chassisnumber**  
VF1FLAHA68Y298526

Technical condition 

**Remarks**  
L1H1, airco, pdc, trekhaak  
( A15 )



**Price €3950**

# KLEYN VANS

**KLEYN GROUP** **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®  
P.O. Box 3  
4214 ZJ Vuren  
Zeiving 12  
4214 KT Vuren  
The Netherlands

IBAN: NL32RABO0317847430  
SWIFT/BIC: RABONL2U

KvK 11044363  
BTW/VAT NL807901337B01

## Equipment

### Chassis

Configuration	4x2
Loading Capacity	1,120 kg
Own weight	1,650 kg
Gross vehicle weight	2,770 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	2,000 kg
Towing bracket	
Wheelbase	310 cm

### Cabin

Airconditioning	
Number of airbags	1
Parking assistance	Back
Electric windows	
Electric mirrors	
Partition	
Color	Multicolored
Metallic	
Heated mirrors	
Lighting type	Halogen lamps
Bluetooth	

### Drivetrain

Engine capacity	84 Kw (114 Hp)
Fuel type	diesel
Euro	4
Distribution type	Timing chain
Gearbox kind	Manual
Number of Gears	6
Power steering	
ABS	
ASR	
Starter battery	

### Superstructure

Build kind	L1H1 - Short wheelbase, Low roof
Inner box length	188 cm
Inner box width	163 cm
Inner box height	112 cm
Load bed height	89 cm
Netto height	106 cm
Roof-rack	None
Sidedoors	1
Back doors	Double door

### Doors

Central locking

### Chairs

Number of seats	3
Seat cover	cloth
Chair adjustment	Manually

### Remarks

Remarks	L1H1, airco, pdc, trekhaak
---------	----------------------------

### Tyres/Wheels

Tire type	All weather tyres
-----------	-------------------

### Contact information




info@kleyn.com  
Tel: +31 183 668 444

### Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

## Dimensions



# KLEYN VANS

**KLEYN GROUP** **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

## Inspection report

### Chassis

Dashboard display codes

Electrical

### Cabin

Internal

External

Steering column

Chassis

Brakes

### Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

### Superstructure

Internal condition

External condition

### Tyres/Wheels

Tyres

## Tires and axles



1

Tire size: 195/65R16  
coil spring suspension  
Disc brakes



2

Tire size: 195/65R16  
coil spring suspension  
Disc brakes

## Contact information



info@kleyn.com

Tel: +31 183 668 444

## Legenda for inspection report

- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements