


Dimensiunile



KLEYN VANS

KLEYN GROUP TRUCKS TRAILERS SERVICES

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Proces verbal de inspecție

asii

Coduri de afișare ale
Electric



Cabin

Interne



Extern



Direcție



Arcuri



asii



Frâne



Angrenaj de transmisie

Motor - generalități



Sistem de răcire



Sistem de alimentare cu carburant



Sistem de evacuare



Sistem de gresare



Cutie de viteze



Ambreiaj



Angrenaj de transmisie



Suprastructur

Condiție intern



Condiție extern



Anvelope/Rotii

Anvelope



Pneuri și axe



M rime envelope: 225/65R16,0
arc elicoidal
Frân cu discuri



M rime envelope: 225/65R16,0
suspensie pe arcuri
Frân cu discuri

Informații de contact



info@kleyn.com
Tel: +31 183 668 444

Explicație pentru raport de inspecție

Foarte bine de stat
 Bun de stat
 De stat rezonabil
 Moderat de stat
 Nu îndeplinesc cerințele